




Poke-Yoke Bodyshop

LTG Symbol rotation

Before



Picture not available

After



Description

- The symbol bracket position was only assured in the Paintshop oven, where the structural glue cured.
- Due to the manual handling operations during the construction process, there was a risk of rotating the symbol bracket unintentionally.
- Add a Weld point in the stosspunkten station

Results and improvements

This improvement created a welding fix between the two parts, making it impossible to create rotation between them and cause a problem.

Facts	
Area	Bodyshop 4
Saving	N/A
Investment	N/A
Implementation date	2022

